



SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

55

SUBJECT: TS-180S LOW 40M ALC

DATE 9/14/79

Some operators may experience intermittent reduction or loss of ALC, especially after several minutes transmit time.

On the LPF unit X51-1180-00, change C14, C17 from 470 pF to 390 pF. Check ALC level and adjust if necessary, per section 406 ALC meter adjustmet, TS-180S service Manual.

New part: CM93D2H390J 390pF +/- 5% 500v mica or ceramic

Please annotate your Service Manual

JEB/yn

▼ LPF UNIT (X51-1180-00)

